

## ESSEX COUNTY OFFICE OF COMMUNITY RESOURCES

7514 Court Street · P.O. Box 217 · Elizabethtown, New York 12932 Telephone (518) 873-3426 · Fax (518) 873-3751

Anna Reynolds Director Rob Wick Project Manager

- TO: All Bidders / Respondents
- FROM: Essex County Community Resources, on behalf of the Town of Moriah
- **DATE:** June 29, 2022

**SUBJECT:** Addendum #2 Moriah Sewer Upgrades Engineering RFQ

1. Questions from interested bidders:

Q: The RFQ and Appendix B discuss Titus Rd Pump Station in the scope, but the required work does not seem to be cited in the recent report addenda or the Capital Improvement Plan; please clarify scope.

A: In 2016, an emergency project was conducted to replace (2) pumps, repair slide rails and few electrical repairs to keep the facility operational. *Proposed scope for the next phase of work is located on the next page*:

END OF ADDENDUM # 2

## SUMMARY OF RECOMMENDED PUMP STATION IMPROVEMENTS

- 1. Resurface the wet well and valve vault with an epoxy concrete coating system.
- 2. Replace the wet well and valve vault frame and hatch to include a new safety hatch.
- 3. Replace existing pumps with upgraded units including controls and appurtenances.
- 4. Replace valves and pipe located in the valve vault.
- 5. Replace existing flow meter.
- 6. Install a new davit crane and base.
- 7. Replace existing doors.
- 8. Replace existing sump pump.
- 9. Provide new wet well level and pump controls.
- 10. Install new panelboards.
- 11. Install new lighting.
- 12. Replace the door and hardware.
- 13. Install door entry alarm.
- 14. Install a new generator and automatic transfer switch.
- 15. Install a new alarm dialer with associated monitoring signals.
- 16. Install new electric unit heaters with new industrial duty units.
- 17. Install new electric unit heaters with new industrial duty units.
- 18. Install new intake louver.
- 19. Install new exhaust fan.
- 20. Install a new intake damper.
- 21. Replace plywood on the interior of the pump station.
- 22. Paint the interior of the pump station.
- 23. Install a new SCADA system with associated monitoring signals (Add-Alternate).
- 24. Paint exterior (Add-Alternate).
- 25. Install new fence (Add-Alternate).